FLA

133

CENTRAL INTELLIGENCE AGENCY

INFORMATION REPORT

This Document contains information affecting the National Defense of the United States, within the meaning of Title 18, Sections 783 and 784, of the U.S. Code, as amended. Its transmission or revelation of its contents to or receipt by an unauthorized person is prohibited by law. The reproduction of this form is prohibited.

	CONTIDENTIAL/CONTROL - 0	S. OFFICIALD CALL	25X1
COUNTRY	Bulgaria	REPORT	
SUBJECT	The Railroad Car Shops at Dryanovo	DATE DISTR.	22 January 1954
		NO. OF PAGES	3
DATE OF INFO.		REQUIREMENT NO.	RD
PLACE ACQUIRED		REFERENCES	25X1
	This is UNEVALUATE	D Information	
	THE SOURCE EVALUATIONS IN THIS REPO THE APPRAISAL OF CONTENT IS (FOR KEY SEE REVERSE)		
	1.01	- 01	25 X 1

CONTRACTOR THE CONTRACT OF CONTRACT ONLY

Location (figures are keyed to Appendix, page 3)

1. The railroad car shops or factory are located along the Dryanovo-Turnovo railroad line (figure A-B), about 700-800 meters northeast of Dryanovo. There is a railroad station for the factory (figure 1) which is 2,500-3,000 meters from the Dryanovo railroad station. The Dryanovo-Turnovo highway passes south of the factory (figure C-D).

2. There are about 20 workers' houses (figure 3) west of the factory compound. The factory property, including these houses, is about 1,500 by 500-600 meters in size. The factory area is about 600 by 400 meters and is enclosed by wire entanglements.

Security

3. An unknown number of Militiamen is stationed at the factory. There is a Militia post at the entrance gate (figure 2). The factory area is lighted by electricity at night to facilitate security controls.

Installations and Production

- the three are three 80 by 50 meter 1-story buildings with skylight roofs. Brakes and heating systems are repaired in one of these (figure 8); carpentry and fitting work is done in another (figure 9); and painting and Morocco work is done in the third (figure 10). There is a 2-story building (figure 7), the first floor of which contains repair shops, and the second floor of which contains the administrative offices. There is an electric power shop (figure 5) and a lathe, drill, and polishing shop (figure 6).
- 5. There are spur lines all about and inside the buildings. Newly-built cars and cars being repaired are parked in the southern section (figure 11).

CONFIDENTIAL/CONTROL - U.S. OFFICIALS ONLY

٢	STATE	¥	ARMY	x	NAVY	x	AIR	x	FBI		AEC	T		
IJ,			MARIT		Lucy.	_=	Livi		لحجنتنا		1		 	
į						1	,			- !				

Wachington Distribution Indicated by "X"; Field Distribution by "#"

Okoliya.			
Personnel and Working Conditions 8. The director is a former partisan, Ivan (lnu), from Bulgarene village, Dryanov	9.		vo,
	8.		
7. The factory builds and repairs only passenger cars.		Personnel and Working Conditions	
	7•	the factory builds and repairs only passenger cars.	25X1 25X1
		generator, an unknown number of borers and drills, "Schlief" polishing machines, "Sheping" honing machines, automatic saws, and planers. There are spray guns in the paint shop.	25 X 1
		-2	
-2-			25X1

- C-D. Dryanovo-Turnovo road.
- 1. Railroad station for the factory.

- 2. Entrance gate.
 3. Workers' houses.
 4. Workers' club and dining hall.
- 5. Electric power shop.
- 5. Electric power snop.
 6. Lathe, drill, and polishing shop.
 7. Repair shops (first floor) and administrative offices (second floor).
 8. Brakes and heating systems repair shop.
 9. Carpentry and fitting work shop.
 10. Painting and Morocco work shop.
 11. Parking for newly-built cars and cars being repaired.

CONFIDENTIAL/CONTROL - U.S. OFFICIALS ONLY

